Post: Contact:
Air Navigation Department
119 Nguyen Son Str.,
Bo De Ward,
Ha Noi, Viet Nam
Tel: +84 24 38274191
Fax: +84 24 38274194
E-mail: and@caa.gov.vn
Web: http://caa.gov.vn

CỤC HÀNG KHÔNG VIỆT NAM
CIVIL AVIATION AUTHORITY OF VIET NAM

AIP SUP
57/26
Có hiệu lực từ
Effective from
20 OCT 2026
Được xuất bản vào
Published on
16 OCT 2026

CÔNG BỐ CHƯỚNG NGẠI VẬT TẠM THỜI TRONG KHU VỰC LÂN CẬN SÂN BAY TẠI CẢNG HÀNG KHÔNG QUỐC TẾ PHÚ QUỐC (VVPQ)

1 GIỚI THIỆU

Tập bổ sung AIP này được phát hành nhằm thông báo về việc công bố chướng ngại vật tạm thời trong khu vực lân cận tại Cảng hàng không quốc tế Phú Quốc (VVPQ).

2 CHI TIẾT

2.1 Phạm vi ảnh hưởng của chướng ngại vật tạm thời

Chi tiết chướng ngại vật (tòa nhà):

– Vị trí: Xâm phạm bề mặt tiếp cận chính xác đường CHC 10L.

– Tọa độ:

Chi tiết xem tại trang 2.

2.2 Thời gian hoạt động: Từ 0000 ngày 20/10/2026 đến 2359 ngày 31/12/2026.

Ghi chú: Chướng ngại vật trên được đánh giá là không ảnh hưởng đến phương thức bay hiện hành.

3 HIỆU LỰC

Tập bổ sung AIP này sẽ có hiệu lực từ 0000 ngày 20/10/2026 đến 2359 ngày 31/12/2026.

4 HUỶ BỎ

Bất kỳ thay đổi nào liên quan đến tập bổ sung AIP này sẽ được thông báo bằng NOTAM.

- HẾT -

PUBLICATION OF TEMPORARY OBSTACLES IN THE AERODROME VICINITY AT PHU QUOC INTERNATIONAL AIRPORT (VVPQ)

1 INTRODUCTION

This AIP Supplement issues notification of the publication of temporary obstacles in the vicinity of Phu Quoc International Airport (VVPQ).

2 DETAILS

2.1 Affected area of temporary obstacles

Details of obstacles (building):

– Position: Penetrating the precision approach surface of RWY 10L.

– Coordinates:

See page 2 for details.

2.2 Operation period: From 0000 on 20 OCT 2026 to 2359 on 31 DEC 2026.

Note: The obstacle above has been evaluated as having no impact on current flight procedures.

3 EFFECTIVE

This AIP Supplement shall become effective from 0000 on 20 OCT 2026 to 2359 on 31 DEC 2026.


4 CANCELLATION

Any change relating to this AIP Supplement shall be notified by NOTAM.

- END -

LAYOUT OF AERODROME CHART DURING BUILDING OBSTACLE AFFECTED PERIOD FROM 0000 ON 20 OCT 2026 TO 2359 ON 31 DEC 2026.

AN GIANG/PHU QUOC INTL (VVPQ)



NOTES:
- THE BUILDING OBSTACLE ABOVE HAS BEEN EVALUATED AS HAVING NO IMPACT ON CURRENT FLIGHT PROCEDURES.
- THIS CHART CONTAINS BUILDING OBSTACLE INFORMATION ONLY. FOR RWY 10L/28R AND NEW TAXIWAY OPERATIONAL DATA: REFER TO AIRAC AIP SUP 54/26.

No.	POSITION OF BUILDING OBSTACLE COORDINATES		HEIGHT	ELEVATION (MSL)
NR 1	10°10'39.91"N	103°58'10.46"E	26.7 M	30.7 M
NR 2	10°10'42.35"N	103°58'08.48"E	26.7 M	30.7 M
NR 3	10°10'42.27"N	103°58'07.71"E	26.7 M	30.7 M
NR 4	10°10'42.77"N	103°58'07.68"E	26.7 M	30.7 M
NR 5	10°10'42.94"N	103°58'09.25"E	26.7 M	30.7 M
NR 6	10°10'40.47"N	103°58'11.29"E	26.7 M	30.7 M
NR 7	10°10'40.42"N	103°58'14.00"E	26.7 M	30.7 M
NR 8	10°10'39.91"N	103°58'13.96"E	26.7 M	30.7 M

